


0 0.225 0.45 0.9 1.35 1.8 Miles
 Produced August 24, 2016 for demonstrative purposes

Ramp Material Map Concord, Massachusetts






Legend

Ramp Compliance

- Compliant
- Not Compliant
- Pre-2012
- Proposed Ramp Location


— Routes

Town Boundaries



Ramp Compliance Map Concord, Massachusetts






Legend

Ramp Condition


- Excellent
- Good
- Fair
- Poor
- Reconstruct

- Routes
- Town Boundaries



**Ramp Condition Map
Concord, Massachusetts**






0 0.225 0.45 0.9 1.35 1.8 Miles
 Produced August 24, 2016 for demonstrative purposes

Sidewalk Conditions Map Concord, Massachusetts





Legend

Material


- Bituminous Concrete
- Portland Cement Concrete
- Brick
- Stone Dust
- Routes
- Town Boundaries



0 0.225 0.45 0.9 1.35 1.8 Miles
Produced August 24, 2016 for demonstrative purposes

**Sidewalk Material Map
Concord, Massachusetts**






0 0.225 0.45 0.9 1.35 1.8 Miles
 Produced August 24, 2016 for demonstrative purposes

Trip Hazards Map Concord, Massachusetts






0 0.225 0.45 0.9 1.35 1.8 Miles
 Produced August 24, 2016 for demonstrative purposes

Pinch Point by Type Map Concord, Massachusetts





Legend

Cross Slope

- 0-2%
- 2-4%
- 4-6%
- 6+%

— Routes


▭ Town Boundaries



0 0.225 0.45 0.9 1.35 1.8 Miles
Produced August 24, 2016 for demonstrative purposes

**Cross Slope Map
Concord, Massachusetts**





0 0.225 0.45 0.9 1.35 1.8 Miles
 Produced August 24, 2016 for demonstrative purposes

Overhead Obstruction Map Concord, Massachusetts

